
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/15/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S01OO_033MH	Test ID: <u>D1032-022032</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01OO_033MH
0			Water Level	
192.8000031	02		Tap Factory	From 2074 Queen Ann
193.1000061			Dye Test Visible	@ TF - cleanout
193.1000061			Dye Test Visible	@ TF - downspout
193.1000061			End of Survey	DYE TEST COMPLETED
193.1000061			Manhole	S03OO_010MH